

# **APPENDIX A**

---

## **Site Photographs – Characterization**



1. 6/2/06 – Northwest Corner (NWC) prior to investigation, looking west; note 35 staked boring locations.



3. 6/2/06 – “Silly putty” material and green-colored soil in sample NWC-1-39.



2. 6/2/06 – NWC soil characterization sample collection, looking west.



4. 7/20/06 – NWC prior to excavation, looking west.